

Message

From: Beslow, Mike [beslow.mike@epa.gov]
Sent: 1/21/2017 4:44:02 PM
To: LT Arnold Paul S [Paul.S.Arnold2@uscg.mil]; LT Cook Lindsay N [Lindsay.N.Cook@uscg.mil]
CC: Fitzgerald Sean [sean.f.fitzgerald@uscg.mil]
Subject: Fwd: question

LTs-

Here is the D9 contact ArcelorMittal worked with for the deflection plates approval. Are you able to reach back regarding the details?

Mike Beslow
On-Scene Coordinator
US EPA, Region 5

Please excuse any errors in this message as it was sent from a mobile device.

Begin forwarded message:

From: "Barnett, Thomas R" <Thomas.Barnett@arcelormittal.com>
Date: January 21, 2017 at 6:13:01 AM CST
To: "Beslow, Mike" <beslow.mike@epa.gov>
Subject: RE: question

Scott Striffler, U.S. Coast Guard, Cleveland District.

Will look up more on the situation at the intake historically on Monday Mike.

Thomas Barnett | Manager, Environmental Technology
ArcelorMittal Indiana Harbor LLC.
ArcelorMittal USA LLC

Environmental Department | 3001 Dickey Road, Sta. 001
East Chicago, IN 46312

T +219 399 2380 | M +219 313 1605 | F +219 399 3211 | www.arcelormittal.com

From: Beslow, Mike [<mailto:beslow.mike@epa.gov>]
Sent: Friday, January 20, 2017 3:53 PM
To: Barnett, Thomas R <Thomas.Barnett@arcelormittal.com>
Cc: Benoit, Simonne T <Simonne.Benoit@arcelormittal.com>
Subject: question

Tom-

Could you please let me know what agency required ArcelorMittal to install the plates at outfall 009 and 010. And who at the agency you worked with?

Also could you please send me the information you have regarding the environmental release you told me that arcelor mittal had in regards to their intake?

Thank you

Mike Beslow

On-Scene Coordinator
US EPA, Region 5
77 W Jackson (SE-5J)
Chicago, IL 60604
voice: (312)353-8678
fax: (312)582-5139